## Identifying Broken and Co PosTensioned Bars and Tra Tendons Purdue Road School March 8, 2011

Siva Venugopalan
Principal Engineer
Siva Corrosion Services (SCS)
Siva@SivaCorrosion.com
www.SivaCorrosion.com




Structure	PT Ro
B-4 00 2 8-6 3 7 A	3 5 1
B-4 00 2 8-6 3 7 B	4 1 6
B-4 00 2 8-6 3 7 C	195
B-4 00 2 8-6 3 8 A	3 1 2
B-4 00 2 8-6 3 8 B	260
B-4 00 2 8-6 3 8 C	283
B-4 00 2 8-6 3 8 D	195
<u>Total R</u> ods	2012

# Opening



ðØPT Rods were installed to develop cor the superstructure over the piers
ðØGeneral conditions of sevefræilr Utoripsoor PT Rod conditions were of particular
ðØOnly the ends of the Rods were acces
ðØInspection difficualticess openings too small, false work from original constr
ðØA number of Rods appeared to experie fracture



- ðØConcerns that some Rods were experi continued corrosion and were possibly
- ðØPast inspections limited to sounding t the ends (when accessible)
- ðØProblemRods may have significant cor yet still sound tgigvhing a false sense security
- ðØRemaining strength of structure deper number of PT Rods still in good condi

- ðØLoad carrying capacity could be reduc certain number of PT Rods were corro
- ðØUnlike RC structures, reduction in PT strength can result in sudden structur
- ðØDepartment placed the structmon ton a inspection cycle
- ðØInspection firm recommended a NDT c for further testing



ðØSolve problems ebærføre problems beco much larger and more costly

> More economical to proactively rep small number of rods instead of performing emergency repairs lat






### Past Inspections:

ðØMore visible corrosion than other Unit ðØA higher number of suspected broken/ ðØSome Rods were ineffective in carryin (loose rod)

### Phased Approach:

- ðØWith 2012 Rods, and limited funding, Rods <u>Phhas</u>es
- ðØBenefit of Phased tæsvtaihugate results a decide best course of action at each s








ðØConstruction detail prohibited visual i of both ends of Rods (in some cases) ðØRods were electrically continuous bec electrical short that exists through th reinforcement

- ðØConnected to both ends of each Rod
- ðØA set amount of current is applied (us computer driven system), and the volt recorded
- ðØResistance of the Rod is calculated u number of factors
- ðØAfter statistical analysis, broken/seve corroded Rods are identified











ðØldentified all rods that had than 97.5% of all rods.


ðØMean: the average value of a data set ðØStandard Deviation: a measure of vari data around the mean


i.e. Are the measurements all about or are there resistance values that significantly from the mean?

ðØProbability: The chance that a particu will (or did) occur

Mean Probability Density

z is the number of standard deviations away from the mea





13.6%

13.6%

~99.7%

13.6%

13.6%

2.1%

2.1%

 $\stackrel{\textstyle (\times)}{\times}$ There is a 97.8% bility: probability of x < = 2 $\boldsymbol{\sigma}$ 9 There is a 50% here is only a 2. 0 probability of probability of Д x > 2X < = 0X





Problem Rods	

## Problem Rods

Cell Numbe	Corroded/Br <b>Rkoedns</b> 95% Confidence Level
2 F	Interior # 9
2 G	Interior # 3
	Interior #4
	Exterior # 11
	Exterior # 13
2 J	Exterior #3
3 A	Interior #3
	Interior #5
3 B	Interior #14
3 C	Interior #5
	Interior #12
3 F	Interior #2
	Interior #7
3 J	Interior #2
	Interior #7
	Interior #9
	Interior #12
	Exterior #1
	Exterior #7
	Exterior #9
3 K	Interior #10
	Interior #12
	Interior #13
	Exterior #5








ðØ21 powder samples were collected ðØ6 of 21 locations exhibited chloride le depth below the corrosion threshold (end)


- ðØThe measured resistances clearly indi number of rods that are broken or sev corroded
- ðØThe mean (¼) and the standard deviat the resistance armen ®and 1.0m4©, respectively
- ðØAbout 8% of rods have experienced si corrosion/section losses
- ðØThe structure can be restored to full severely corroded rods are identified replaced soon


- ðØGPR was effective in identifying reinf well as the boundaries of the boxes
- ðØChloride contamination in the shiplap
- ðØCorrosion of the reinforcement and re concrete damage will continue and ac
- ðØCorrosion will lead to expensive repa addressed soon


- ðØRemove and replace all rods identifie significantly corroded or already brok
- ðØAfter removal, correlate measured sed to measured resistances and determin correlation coefficient, if any
- ðØPerform additional analysis of Unit 38 the correlation coefficient and identifor rods that may be severely corroded.
- ðØPerform similar resistance testing on to determine the integrity of the PT re

- ðØPerform additional chloride testing aw shiplap region and on the top slab to the extent of contamination throughou structure
- ðØInstall a corrosion protection system further damage to the structure
- ðØPerform an NDT evaluation of the top (chloride contamination of deck is hig










ð@Performed tests at si and in laboratory ðØQ uantified the extent causes of corrosion ðØD e signed a Cathodic Protection System to e service lives of piles ð@Ruled out unnecessar mitigation measures (Owner saved costs)


Problems:

ð§/isible strand cormosiennot yet
visible?

ð\re there tools that can accurately the condition?


ð§s preservation possible in this cas





ðØThe owner better understood proper combinations of NDT tools needed to: Quantify existing deterioration Predict the future deterioration of b

## Closing: About SCS



## Thank You

## Questions?

Siva Venugopalan
Principal Engineer
Siva Corrosion Services (SCS)
Siva@SivaCorrosion.com
www.SivaCorrosion.com